

# STRUCTURAL PERFORMANCE

performance issues relative to extreme events

## Tuscaloosa Tornado

### Preliminary Observations on Wood-Frame Buildings Damage Assessment

By Dr. David O. Prevatt, P.E.,  
Dr. John van de Lindt,  
Dr. Rakesh Gupta and  
Bill Coulbourne, P.E.

*The damage inspection team members were: Dr. David O. Prevatt, P.E. (Univ. of Florida), Leader; Dr. John van de Lindt (Univ. of Alabama), Dr. Rakesh Gupta (Oregon State Univ.), Dr. Andrew Graettinger (Univ. of Alabama), Dr. Shiling Pei, P.E. (South Dakota State Univ.), Sam Hensen, P.E. (Simpson Strong-Tie), Bill Coulbourne, P.E. (Applied Technology Council), Thang Dao (Univ. of Alabama), Dr. David Grau (Univ. of Alabama) and graduate and undergraduate civil engineering students from the University of Florida, University of Alabama, Iowa State University and Clemson University.*



A forensic team, consisting of university engineers and scientists as well as industry professionals, surveyed the structural damage to wood-frame buildings caused by the April 27<sup>th</sup> tornado that ripped through the city of Tuscaloosa, home to the University of Alabama. The tornado cut approximately a 1/2-mile-wide swath through a densely populated urban area that consisted mainly of older 1930s to 1970s residential buildings and

light commercial structures, with some newer multi-family structures scattered throughout. This was a powerful tornado that the National Weather Service (NWS) suggested was on the ground for nearly 90 minutes, causing damage from Tuscaloosa to North Birmingham. The NWS preliminary estimate of maximum wind speeds was around 190 mph, but a significant area of damage was caused by wind speeds estimated to be below 135 mph. Approximately 5,000 buildings were lost and some 500 businesses were directly affected. Over a period of six days, the team looked at hundreds of homes and other structures. Initial observations of the structural damage, and possible mitigation approaches to save lives and reduce losses in the future, can be summarized as follows.



Figure 1: Toe-nailed connection for truss.

Many of the failures of older buildings can be attributed to the lack of continuous vertical and/or lateral load paths, not just excessive wind speeds. In a series of perpendicular transects to the tornado's path, the team observed a gradual reduction in severity of damage from the center of the path towards the edges. There was complete destruction, with some houses shifted entirely off their foundations, at the center of the path. A short 100 to 200 yards away, major structural components such as roof trusses and walls failed, but the building remained in place. Beyond 200 yards, houses had severe siding damage, loss of roof covering, broken windows and failed patio/porch roofs. Many of the buildings at the outer boundaries of the damage zone had a discontinuity in vertical load paths created by inadequate connections at critical locations. This is not surprising, given the age and location of these buildings in a non-hurricane area where no building code mandates special attention to such details.



Figure 2: Carport column uplift failure.

The study team found numerous instances where detailing in accordance with current building codes for hurricane-prone regions would have reduced the damage and potentially reduced injuries. Examples of damage included roof loss due to inadequate toenailed connections for trusses or rafters (Figure 1), porch or carport column uplift failures (Figure 2), and the attachment of sill plates with only concrete cut nails (Figure 3). The team also observed a lack of connections at the wall boundaries that may have contributed to the loss of exterior walls, especially when the building envelope was breached and the walls were pressurized from the inside (Figure 4, page 26). Many of these buildings were built before the existence of manufactured connectors that better provide a continuous load path. In addition, as expected in a tornado, windborne debris created many penetrations and openings through the building envelope.

For tornadoes of low to moderate intensity (EF0-EF2), it may be possible to save lives and reduce injuries by employing load path enhancement techniques known to work in hurricane-prone regions. At the moment, such measures would be optional for owners, but they need to be fully understood by builders and building code officials so that, for those who want them, the quality of the construction and inspections ensures improved building performance should the building be impacted by a tornado.

During the damage investigation, the team also observed that there might be a minimum size (square footage) building that provides enough interior wall lines to create a safer space somewhere in the middle of a light-frame wood structure. Small houses have fewer interior walls to help either resist uplift (if tied to the roof) or act as barriers to missile impacts and extreme wind pressures. Larger homes typically have more interior walls that could be used for increased lateral resistance, additional missile protection or improved interior shelter of occupants. There can be a safe location within wood frame construction if the walls remain standing and the roof stays in place in spite of building envelope failure, such as glass breaking and/or garage doors imploding.

The team observed that for the highest tornado wind speeds (EF5), even new buildings built to more recent building codes were completely destroyed, as one might anticipate given that the forces are in excess of four to five times the design values. Figure 5 (page 26) shows

an apartment complex that was completed in 2010 and was about half occupied at the time of the tornado. The whole facility was damaged extensively because it was in the direct path of the tornado and wind speeds increased even further because of the terrain, which consisted of hills on all sides. Evidence suggests that the structures were likely designed and built according to the 2006 IBC, with hurricane clips between trusses and the top plates, code-required nailing of roof and wall sheathing, and anchor bolts in exterior wall sill plates every four to six feet. Part of the complex



Figure 3: Evidence of cut nail at sill plate.

# The Results Are In...

Our Epcon G5 Epoxy outperforms the competition in outdoor applications with excellent spacing and edge distance data – making it the most versatile adhesive suitable for extreme weather conditions. After further extensive examination and testing, the ICC Evaluation Service certifies the G5 Epoxy now complies with the 2009 International Building Code.



Now Meets 2009 IBC Requirements

ADVERTISEMENT - For Advertiser Information, visit [www.STRUCTUREmag.org](http://www.STRUCTUREmag.org)

Securing America's Infrastructure Since 1910 [www.itwredhead.com](http://www.itwredhead.com)



Figure 4: Pressurized exterior wall.



Figure 5: Catastrophic damage at apartment complex.

was leveled down to a clean concrete slab, where even linoleum flooring was removed. This illustrates the difficulty of designing a wood frame building economically that can resist the effects of the most severe tornado wind speeds.

The team strongly believes that structural engineers should not simply accept the fact that people will perish in their homes from a tornado because the wind speeds are too high, and thus there is nothing that we can do. At the lower tornado wind speeds associated with EF0-EF2 events, there are known construction practices that could be used to enhance the robustness of typical light-frame buildings. One solution already practiced in "tornado alley" is the installation of safe

rooms, but this life-saving measure is not yet widely used. The team believes that other building strengthening practices for these types of events should be developed, and then demonstrated by local builders and building officials so that owners who want to reduce their risk of injury or death from tornadoes are able to do so.■

This material is based upon work supported by the National Science Foundation. Any opinions, findings, and conclusions or recommendations expressed in this material are those of the authors and do not necessarily reflect the views of the National Science Foundation.

ADVERTISEMENT - For Advertiser Information, visit [www.STRUCTUREmag.org](http://www.STRUCTUREmag.org)

Restoration Team Experience Since 1978

Masonry Façade Re-Anchoring Solutions


# SAVE THE WALL!

*Don't Tear it Down or Cover it with Insulation and Stucco*

Strengthen and stabilize masonry façades while adding veneer stiffness for added decades of protection and comfort. CTP has engineered anchor performance solutions for claddings of brick and stone. A selection of corrosion resistant products are available to re-anchor brick to wood, concrete, steel, block, brick, metal stud, or tile back-ups.

### CTP Stitch-Tie


Helical Wall Tie System for Stabilizing Veneers and Crack Repair



Proudly Made in the USA!

### CTP Stone-Grip

Mechanical Anchors for Stabilizing Stone Panel Veneers



ANOTHER CTP ORIGINAL!

**NEW!**  
CTP GRIP-MAX<sup>®</sup>  
\* Patent Pending

### CTP Grip-Tie

Mechanical Repair Anchors for Stabilizing Veneers



### CTP CT-16

For Brick Additions or Replacement; and for Brick Veneer Stud Cavity Wall Construction. Veneer Anchoring System That Keeps the Air Barrier Intact and the Veneer in Place.



Shown Here With:

**CTP Wall Tie**  
a Multifunctional Triangle Wall Tie That Can be Used in Standard or Seismic Veneer Anchoring Applications

Contact our Technical Services Team with your repair application needs for a cost effective and performance targeted veneer stabilizing solution.

Construction Tie Products, Inc. is committed to supplying the highest quality masonry tie and construction systems in North America and satisfying all stringent national codes and standards for today's building structures. CTP, Inc. promises to be a reliable product source along with on-time business integrity for all demanding builders.



7974 W. Orchard Drive  
Michigan City, Indiana  
46360-9390 • USA  
Phone: (219) 878-1427  
Contact: Steve Getz, BSCE  
[www.ctpanchors.com](http://www.ctpanchors.com)

Engineered Anchoring Solutions Provider